



# BOAT DETAILING SERVICES

T O P S I D E:

## TOPSIDE SILVER PACKAGE (above rub rail):

Entire boat washed from rub rail up (smooth and non-skid surfaces, includes transom and swim platform)  
 All seats deep scrubbed and stains removed to the best of our ability  
 Equipment and console cleaned  
 Oxidation and industrial fallout removed from all smooth surfaces (high speed polishing)  
 RejeX polymer sealant is applied to all smooth fiberglass surfaces  
 All plastic windows and surfaces cleaned only (console area, door to cabin, hatches, etc...)  
 All glass windows cleaned inside and out  
 Groves in storage compartments and pull up doors cleaned  
 All stainless steel and chrome polished

**Priced at \$23.75 per linear foot, plus sales tax**

## TOPSIDE GOLD PACKAGE (above rub rail):

Entire TOPSIDE SILVER PACKAGE  
 All storage compartments cleaned and stains removed  
 All carpets on exterior of boat will be vacuumed and cleaned with an extraction system  
 Protector applied to seats to waterproof and prevent dirt build-up  
 All plastic windows (isinglass) are also polished  
 Rain-X applied to all front windows

**Priced at \$26.50 per linear foot, plus sales tax**

## ADDITIONAL BRIDGE LEVEL: (includes the inside and outside of the bridge level)

**Priced at \$4.75 (SILVER) / \$5.25 (GOLD) per linear foot, plus sales tax**

H U L L:

## HULL PACKAGE: (includes all fiberglass on hull & fiberglass under swim platform) - (below rub rail)

Hull of boat washed and stains removed  
 Oxidation removed on hull (compounding and polishing)  
 RejeX polymer sealant is applied to hull

**Priced at \$14.25 per linear foot, plus sales tax (bottom painted boats)**

**Priced at \$19.25 per linear foot, plus sales tax (bottom is all gel coat) (includes blocking/de-blocking of boat)**

**Add \$100.00 if boat needs to be power washed, plus sales tax**

**Add \$150.00 if boat needs to be acid washed, plus sales tax**

## BOTTOM PAINT REFINISHING SILVER:

(NOTE: Length = Total length of boat without swim platform / Beam = Widest beam of boat at rub rail)

Bottom surface will be lightly sanded and the surface rinsed  
 One coat of Interlux bottom paint will be applied to the bottom (other paints available upon request)

**Interlux VC 17m: Priced at \$4.75 per square foot (beam x length) - plus sales tax**

**Interlux Micron CSC: Priced at \$5.25 per square foot (beam x length) - plus sales tax**

## BOTTOM PAINT REFINISHING GOLD:

Bottom surface will be sanded down completely to the gel coat  
 Bottom will be painted with Interlux protect 2000E until 10 mil thickness (4-5 coats)  
 Two coats of Interlux bottom paint will be applied to the bottom (other paints available upon request)

**Interlux VC 17m: Priced at \$8.75 per square foot (beam x length) - plus sales tax**

**Interlux Micron CSC: Priced at \$9.25 per square foot (beam x length) - plus sales tax**

**INTERIOR - CLEANING & PROTECTING (sleep area(s), galley and head):**

1. Sinks and toilets will be cleaned
2. All vinyl and leather seats will be cleaned
3. All fiberglass will be cleaned, polished and protected
4. All carpet will be vacuumed, pre-spotted and cleaned with an extraction system
5. All stainless will be cleaned and polished
6. All plastic surfaces will be cleaned and polished with a plastic polish (hatches, doors, etc...)
7. All glass, mirrors and wood will be cleaned

**Priced at (please initial):**

|                            |                            |
|----------------------------|----------------------------|
| _____ 20' - 25' = \$210.00 | _____ 41' - 45' = \$380.00 |
| _____ 26' - 30' = \$245.00 | _____ 46' - 50' = \$410.00 |
| _____ 31' - 35' = \$285.00 | _____ 51' - 55' = \$480.00 |
| _____ 36' - 40' = \$340.00 | _____ 56'+ = Custom Quote  |

**ADDITIONAL ITEMS (priced at \$72.00 per hour, plus \$80.00 trip charge - if not being done with other work):**

- \_\_\_\_\_ 1. Teak wood sanding and refinishing
- \_\_\_\_\_ 2. Removal/application of decals, striping, name, etc...
- \_\_\_\_\_ 3. Ozone treatment to remove odors on interior (\$90.00)
- \_\_\_\_\_ 4. Engine compartment wiped and vacuumed out
- \_\_\_\_\_ 5. Bilge area cleaned out
- \_\_\_\_\_ 6. Trim tab refinishing
- \_\_\_\_\_ 7. Propeller refinishing
- \_\_\_\_\_ 8. Rain-X applied to windows
- \_\_\_\_\_ 9. Protector applied to seats to waterproof and prevent dirt build-up

**PERSONAL & BOAT INFORMATION:**

First Name: \_\_\_\_\_ Last Name: \_\_\_\_\_

Home Address: \_\_\_\_\_

City: \_\_\_\_\_ State: \_\_\_\_\_ Zip Code: \_\_\_\_\_

Home Phone: \_\_\_\_\_ Cell Phone: \_\_\_\_\_ E-Mail: \_\_\_\_\_

Manufacturer: \_\_\_\_\_ Length: \_\_\_\_\_ Beam: \_\_\_\_\_

Model: \_\_\_\_\_ Name of Boat: \_\_\_\_\_ Model Year: \_\_\_\_\_

Marina: \_\_\_\_\_ Dock #: \_\_\_\_\_ Launch/Pull Date: \_\_\_\_\_

**Terms and Conditions:**

1. All boats are detailed on a first-come, first-serve basis.
2. All questions and concerns the customer has need to be discussed with GK's within 48 hours after completion of boat detailing because of weather that could adversely affect the look of the boat.
3. All charges incurred by marina or launch fees will be passed onto customer.
4. Payment of bill needs to be received by GK's Custom Polishing, Inc. within 15 days of customer receiving invoice. If payment is not received within 30 days of customer receiving invoice, customer authorizes GK's Custom Polishing, Inc. to charge remaining balance due to their credit card on file.
5. A minimum of \$150.00 worth of work needs to be completed on each boat for their not to be an additional trip charge. A \$150.00 deposit needs to be received from customer before work is started on their boat.
6. **If boat is in abnormally bad condition, the owner will be contacted with any additional charges before GK's Custom Polishing, Inc. begins detailing their boat.**

I have agreed to the above and I have initialed all items of work I would like to have performed.

Contractual Acceptance by: \_\_\_\_\_  
Name Signature Date

Phone: 440-937-4457

Fax: 440-937-7941

E-mail: sales@gkspolishing.com

Mail: GK's Custom Polishing, Inc., 1215 Lear Industrial Parkway, Avon, Ohio 44011